

## Calibrating instruction

Indication on Display	
CAL	<p>Press the „<b>change</b>“ button, after a few seconds the value of the calibration weight appears in the display.</p> <p>Place the calibration weight on the middle of the scale pan.</p> <p>Display disappears.</p> <p>After a few seconds appears --- 200,000 g</p>